



## BOLL WEEVIL TRAP ASSEMBLY



1. ATTACH FUNNEL TO CANISTER. With canister opening facing downward, snap funnel tabs into slots on top of canister.



2. LURE PLACEMENT. Remove lure from foil pouch and place inside of cylinder. Do not touch lures; use forceps for handling.



3. TOP CYLINDER PLACEMENT. Cylinder fits over tip of funnel. Place cylinder tabs into funnel slots turning clockwise to secure.



4. COMPLETION OF TRAP.

Distributed by:  
Great Lakes IPM, Inc.  
10220 Church Rd NE  
Vestaburg MI 48891

989-268-5693  
800-235-0285  
FAX: 989-268-5311

[www.greatlakesipm.com](http://www.greatlakesipm.com)  
E-mail: [glipm@greatlakesipm.com](mailto:glipm@greatlakesipm.com)